Common problems and solutions for milling

Failure \ Main points of solution and inspection			Selection of tool material		Cutting condition					Tool shape								Machine clamping system		
			Material with higher hardness	Material with perfectt oughness	Cutting speed	Feed rate	Cutting depth	Change the diameter and width of milling tools	Cutting liquid	Rake angle	Approach angle	Strength of cutting edge	Number of teeth	Increase the width of chip pocket	Examine the geometry shape of Minor cutting edge.	check the end face run-out	Improve the rigidity of tool	Clamping system of workpiece	Overhang of tool	Power, gap
Fracture of tool nose	Severe abrasion on clearance face	Improper cutting condition			↓				✓											
		Unsuitable geometry shape of cutting edge	✓							↑		↓								
	Severe abrasion on rake face	Improper cutting condition			↓	↓	↓		✓											
		Unsuitable geometry shape of cutting edge	✓							↑	↓	↓								
	Fracture of cutting edge	Improper cutting condition				↓	↓													
		Unsuitable geometry shape of cutting edge		✓							↓	↑			✓	✓	✓	✓	✓	✓
	Thermal cracking	Improper cutting condition			↓	↓	↓		✓											
		Unsuitable geometry shape of cutting edge								↑		↓								
	Build-up edge	Improper cutting condition			↑	↑			✓											
		Unsuitable geometry shape of cutting edge								↑		↓								
Machining precision	Bad surface roughness	Abrasion of tool Great vibration of milling tool	✓		↑	↓	↓		✓			↓			Wiper	✓				
	Burrs occuring	Unsuitable geometry shape of cutting edge			↓	↓	↓	✓												
		Improper geometry shape of cutting edge								↑	↑	↓			✓					
	Side collapse	Unsuitable geometry shape of cutting edge				↓	↓													
		Unsuitable geometry shape of cutting edge								↑	↓	↓	↑		✓		✓			
	Planeness and parallelism deterioration	Improper geometry Improper technique				↓	↓			↑	↑		↓		✓	✓	✓	✓	✓	✓
Other	Great vibration	Cutting condition Improper technology			↓	↓	↓	✓		↑	↑	↓					✓	✓	✓	✓
	Chips twisting and jamming	Improper cutting condition			↑	↑↓		✓	✓				↓							
		Unsuitable geometry shape of cutting edge								↑			↓	✓						