



INDUSTRIAL STRENGTH CONCENTRATE

DILUTION CHART

(SUGGESTED DILUTION RATIOS, STARPOWER TO WATER.)

AIRCRAFT	1:5	INK STAINS	1:2
AUTOS AND TRUCKS	1:20	MACHINERY	1:3
BLOOD	1:4	MEAT AND POULTRY PLANTS	1:20
CARBON BLACK	1:2	MILDEW	1:2
COOKING EXHAUST HOODS	1:3	OIL STORAGE TANKS	1:2
COSMOLINE	1:2	OLD OIL STAINS	FULL STRENGTH
ENGINE PARTS (PARTS WASHING)	1:3	PAINT (OIL OR WATER BASED)	1:1
FLOOR WAX BUILDUP	1:2	PETROLEUM PRODUCTS	1:2
FOOD PROCESSING EQUIPMENT	1:3	PRINTING EQUIPMENT	1:2
GRAFFITI	1:2	RUST STAINS	1:2
GREASY ENGINES	1:2	SOOT ON ENGINE EXHAUST PORTS	1:2
GREASY OR OILY FLOORS	1:20	TILE	1:20
HARD WATER DEPOSITS	1:3	TRAIN ENGINES AND CARS	1:5
HOSES	1:5	TUBS, SINKS AND BASINS	1:3