

## Toyota/Lexus/Scion ECU and OBD-II Reset Plug Installation Procedure

Please be sure that all pre-existing issues with the vehicle have been repaired prior to installing the new ECU to avoid any possible damage to internal components. Damages caused to the ECU due to vehicle issues are not covered under our warranty.

1. Remove the key from the ignition & disconnect both battery terminals
2. Remove the old ECU and install the new ECU
3. Reconnect both battery terminals
4. Insert the OBD-II Reset Plug to the vehicle's OBD-II port
5. Turn ignition to the 'ON' position (do not start engine)  
*(Key-less Start Vehicles: press start button once, do not press brake pedal)*
6. After 30 minutes turn ignition to the 'OFF' position  
*(Key-less Start Vehicles: press start button once, do not press brake pedal)*
7. Remove the OBD-II Reset Plug
8. Start the vehicle

Note: This procedure requires that the original immobilizer is installed.

Once you have completed the ECU installation, please return the old ECU and the OBD-II Reset tool using the pre-paid UPS return label included. Failure to return either module will void the warranty and you will be subject to a \$100 core charge each.

If you are in need of Technical Assistance you can reach our support staff easily by visiting [www.AllComputerResources.com](http://www.AllComputerResources.com) and clicking the *Support* tab.

