


Troubleshooting Guide 4x4 Two-Seater:

Possible reasons for Rear Axle been too short



1. Bushing is not in place

Correct and Incorrect bushing placed

This is the correct space for the hat nut to install.

After twist and lock in the wheel cover, there is no gap between the wheel cover and wheel.

Incorrect) Gap between the wheel cover and wheel.



2. Wheel cover is not in place

Correct and incorrect wheel cover in place.

